



SPRINGBANK LINKS  
GOLF CLUB

# Repair Cost List

## Golf Carts

The below costs are the current Fair Market Value for repair/replacement For parts and labour for any damage caused by, or to, a rented Golf Cart as per an Agreement/Waiver required to be signed prior to driving a Golf Cart. A relevant credit card is required as security and will be charged if damage occurs. Please drive safe.

<b>PARTS:</b>	<b>COST:</b>
Bumper (front).....	\$225
Bumper (rear).....	\$150
Windshield.....	\$375
Front Cowl (body).....	\$450
Rear Cowl (body).....	\$650
Steering Rack.....	\$300
Custom Rim & Tire (1).....	\$200
Roof Supports/Canopy.....	\$750
Rain Cover.....	\$450
Cooler.....	\$ 75
Seat Bench.....	\$825
Seat Back.....	\$650
Other parts.....	@ FMV
Total Cart Replacement Value.....	\$15,000
Repair Labour.....	\$75/hour

**Drive safe to prevent injury & damage. Enjoy a safe round!**