

Repair Cost List

(Golf Carts & Golf Bikes)

The below costs are the current fair market value for repair and replacement of any damage caused by, or to, a rented Golf Cart or Golf Bike as per Agreement prior to driving a Cart or Bike. A relevant credit card is required as security and will be automatically charged the applicable amount(s) if any damage shall occur.

PARTS

Bumper (Front).....	\$225
Bumper (Rear).....	\$150
Front Cowl (body).....	\$450
Rear Cowl (body).....	\$650
Windshield.....	\$375
Steering Rack.....	\$300
Alloy Rim & Tire.....	\$300
Roof Supports/Canopy.....	\$750
Rain Cover.....	\$450
Cooler.....	\$150
Seat Bench.....	\$825
Seat Back.....	\$675
Other parts.....	\$TBD at FMV

Total Cart Value..... \$17,000

Repair Labour.....\$75/hour

Drive safe to prevent injury and damage.