



SPRINGBANK LINKS
GOLF CLUB

Repair Cost List

Golf Carts

The below costs are the current Fair Market Value for repair/replacement for parts and labour on damage caused by, or to, a rented Golf Cart as per our Agreement/Waiver required to be signed by the driver prior to driving a Golf Cart. A relevant credit card is required as security and will be charged should any damage occur. Please drive safe.

| PARTS: | COST: |
|--|---------------|
| Bumper (front)..... | \$225 |
| Bumper (rear)..... | \$200 |
| Windshield..... | \$375 |
| Front Cowl (front body)..... | \$550 |
| Rear Cowl (rear body)..... | \$850 |
| Steering Rack (from hitting curb/rocks)..... | \$450 |
| Custom Rim & Tire (one)..... | \$200 |
| Roof Supports/Canopy..... | \$750 |
| Rain Cover..... | \$450 |
| Cooler..... | \$ 75 |
| Seat Bench..... | \$825 |
| Seat Back..... | \$650 |
| Other parts..... | @ FMV |
| Total Cart Replacement Value..... | \$15,500 |
| Repair Labour..... | \$75/hour |

Drive safe to prevent injury & damage. Enjoy a safe round!

01/06/2026